



Northern States Power Company

414 Nicollet Mail Minneapolis, Minnesota 55401 Telephone (612) 330-5500

March 14, 1983

Regional Administrator Region III U S Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

> PRAIRIE ISLAND NUCLEAR GENERATING PLANT Docket No. 50-282 License No. DPR-42

Failure of a Hot Leg Loop B Sample Isolation Valve - Update Report

The License Event Report for this occurrence is attached.

This event was reported in compliance with Technical Specification 6.7.B.2.(b) since it placed the plant in a degraded mode as permitted by limiting conditions of operations. A revised Licensee Event Report is attached indicating additional problems with this valve.

David Musolf

Manager - Nuclear Support Services

Limon Februar

DMM/SAF/bd

cc: NRC Document Control Desk (1)

NRC Resident Inspector

MPCA

Attn: J W Ferman

Attachments

8303220213 830314 PDR ADDCK 05000282 PDR S

MAR 17 1983 1822