

Appendix A

NOTICE OF VIOLATION

St. Lukes Hospital

License No. 34-17056-01

As a result of the inspection conducted on February 24, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 18 states that the licensee shall possess and use licensed material in accordance with statements, representations, and procedures contained in application dated August 7, 1981.

Application dated August 7, 1981, requires that packages containing radioactive material be opened in accordance with the procedures contained in Appendix F of Regulatory Guide 10.8.

Item 2.f of Appendix F requires that the external surface of final source container be wiped to check for contamination.

Contrary to the above, as of February 24, 1983, no wipe tests have been performed on incoming molybdenum-99/technitium-99m generators received by the licensee on a weekly basis.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

3/16/83
Dated

for S. R. Jasuk
D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2