

BOSTON EDISON COMPANY
GENERAL OFFICES 800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

A. V. MORISI
MANAGER
NUCLEAR OPERATIONS SUPPORT DEPARTMENT

September 22, 1982

BECO. Ltr. #82-252

Mr. Domenic B. Vassallo, Chief
Operating Reactors Branch #2
Division of Licensing
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

License No. DPR-35
Docket No. 50-293

NUREG 0619: Clarification of Completion Date

Reference (A): Boston Edison letter dated August 21,
1981 from Mr. A. V. Morisi to Mr. T. A.
Ippolito

Dear Sir:

Reference (A) described the reasons Boston Edison wished to perform any necessary modifications to the Control Rod Drive System concurrent with modifications to the feedwater system. We gave June 30, 1983 as the date of final implementation for modifications to both systems. This date was chosen because it corresponded to our 1983 refueling outage.

The length of our last refueling outage has impacted upon the commencement of the 1983 refueling outage. We wish therefore to redefine our commitment. Final implementation of the above modifications will be completed prior to restart following the 1983 refueling outage. We appreciate your attention to this issue. Should you require any further information regarding it, please contact us.

Very truly yours,

A. V. Morisi

A001