



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

September 23, 1982


Director
Office of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60

Response to Request for Additional Information
Related to Masonry Wall Design (IE Bulletin 80-11)

In a letter dated August 12, 1982 from Mr Robert A Clark, Chief, Operating Reactors Branch #3, Division of Licensing, USNRC, we were requested to supply additional information related to our response to IE Bulletin 80-11, "Masonry Wall Design". Responses to the 12 items in the enclosure to Mr Clark's August 12, 1982 letter are attached. An additional ten copies of drawing NF-38504-1 (part of response to item 12) are provided.

We believe the enclosed material fully addresses the August 12, 1982 request for additional information. All actions required by IE Bulletin 80-11 have been completed at the Prairie Island Nuclear Generating Plant.


David Musolf
Manager of Nuclear Support Services

DM:/bd

cc: Regional Administrator-III, NRC
NRR Project Manager, NRC
NRC Resident Inspector
G Charnoff

Attachment

Aperture Band Dist

*A001
1/10 Damage
Res'd*

8209280022 820923
PDR ADDCK 05000282
G PDR