

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 0 | R | T | N | P | L | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ 5  
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39

CON'T  
0 | 1 | REPORT SOURCE | L | 5 | 0 | 5 | 0 | - | 0 | 3 | 4 | 4 | 7 | 0 | 8 | 2 | 0 | 8 | 2 | 2 | 8 | 0 | 9 | 0 | 3 | 8 | 2 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 | BOTH TRAINS OF THE AUTOMATIC SAFETY INJECTION SIGNALS WERE BLOCKED FOR 43  
03 | HOURS WHILE IN MODES 3 and 4 WHICH IS IN EXCESS OF THE 6-HOUR LIMIT  
04 | SPECIFIED IN STS LIMITING CONDITION FOR OPERATION, PARAGRAPH 3.3.2.1.  
05 | THIS PREVENTED THE AUTOMATIC ACTUATION OF EMERGENCY CORE COOLING FOR THE  
06 | DURATION OF THIS EVENT.  
07 | \_\_\_\_\_  
08 | \_\_\_\_\_

09 | SYSTEM CODE | S | F | 11 | CAUSE CODE | A | 12 | CAUSE SUBCODE | A | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP SUBCODE | S | 15 | VALVE SUBCODE | Z | 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 | LER/RO REPORT NUMBER | 8 | 2 | EVENT YEAR | 8 | 2 | SEQUENTIAL REPORT NO. | 0 | 1 | 5 | OCCURRENCE CODE | 0 | 1 | REPORT TYPE | 1 | 1 | REVISION NO. | 0 |  
21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN | H | 18 | H | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | ATTACHMENT SUBMITTED | N | 23 | NRC-4 FORM SUB. | N | 24 | PRIME COMP SUPPLIER | N | 25 | COMPONENT MANUFACTURER | W | 1 | 2 | 0 | 28  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

*per telcon Gary Bair 9/14/82*

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 | APPARENT CAUSE WAS ATTRIBUTED TO PERSONNEL ERROR IN THAT OPERATING SHIFT  
11 | PERSONNEL WERE UNFAMILIAR WITH STS REQUIREMENT TO HAVE BOTH TRAINS OF  
12 | AUTOMATIC SAFETY INJECTION WHEN ENTERING MODE 4. REACTOR TRIP BREAKERS  
13 | WERE CLOSED WHICH RETURNED BOTH TRAINS OF AUTO SI.  
14 | \_\_\_\_\_

15 | FACILITY STATUS | C | 28 | % POWER | 0 | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | CONTROL BOARD WALKDOWN | 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
16 | ACTIVITY CONTENT | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER: Gary G. Bair ( DJK ) PHONE: 503/556-3713 Extension 234

8209280263 820903  
PDR ADOCK 05000344  
S PDR

*Note Corrections - Item 29  
Item 29*

*IE 29*