

26

MISADMINISTRATIONS FOR WISCONSIN FROM 1/1/81 TO PRESENT

FEB 04, 1983

8303240253 830218
PDR FDA
STEDOFF LEB3-64 PDR

TYPE	INCIDENT DATE	REPORT DATE	DATE RECEIVED	NAME	LICENSE NUMBER	DOCKET
REGULATION OR LICENSE CONDITION						
DESCRIPTION						
BLANK						
BLANK						
L	120982	121082	122082	LUTHER HOSPITAL	48-02122-04	03000540
35.43	DIAG. PT RECEIVED DOUBLE DOSE OF 16.5 MCI OSTEOSCANMDP.					

L	070982	070982	071682	ST. MICHAEL HOSPITAL	48-02435-01	03003431
35.43	DIAG. PT RECEIVED MAA INSTEAD OF PYP.					

L	102682	102682	110882	ST. MICHAEL HOSPITAL	48-02435-01	03003431
35.43	DIAG. WRONG PT INJECTED 20 MC TC99M MDP FOR HONE SC.					

L	091482	091482	100682	WAUKESHA MEM HOSP	48-06239-01	03003453
35.43	WRONG PATIENT INJECTED WITH 23.2 MCI 99 TC MDP.					

L	091482	091482	120182	WAUKESHA MEM HOSP.	48-06239-01	03003453
35.43	DIAG. WRONG PT INJECTED 23.2 MCI 99MTC MDP.					

L	092382	092982	100182	MARSHFIELD CLINIC	48-10966-03	03008688
35.43	DIAG. PT GIVEN 4MCI TC99 OSTEOLITE INSTEAD OF 4MCITC99M SUL.COL.					

L	072282	100682	100782	NORTHWEST GEN HOSP	48-16749-01	03011581
35.43	DIAG. PT INJECTED TC99M MET,DIPH INSTEAD OF TC99MSC.					

L	100882	100882	111682	ST. ALPHONSUS HOSP.	48-17393-01	03012682
35.43	DIAG. WRONG PATIENT INJECTED 22.5 MCI 99MTC DTPA.					
