



**LOUISIANA**  
POWER & LIGHT


142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

March 21, 1983

L. V. MAURIN  
Vice President Nuclear Operations

W3I83-0092  
Q-3-A35.07.54

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency Report No. 54  
"Tube Steel (HT 16600) Laminations"  
Fifth Interim Report

REFERENCE: LP&L letter W3I83-0058 dated February 17, 1983

Dear Mr. Collins:

At the present time, corrective action modifications and review are expected to be completed by May 6, 1983. A final report will therefore be submitted by May 16, 1983.

Very truly yours,

*L. V. Maurin*  
L. V. Maurin

IE-27

LVM/MAL:keh

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 3) Mr. E. L. Blake
- 4) Mr. W. M. Stevenson