




# Nebraska Public Power District

COOPER NUCLEAR STATION  
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321  
TELEPHONE (402) 825-3811

CNSS942237

June 2, 1994

L. J. Callan  
U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011



Subject: NRC Inspection Report 50-298/94-08


Dear Mr. Callan:

I have reviewed the subject inspection report wherein a non-cited violation for failure to implement adequate security compensatory measures is discussed. As mentioned, the Inspector concurred with our corrective actions and that the occurrence appeared to be an isolated event. Although I am confident that the on duty alarm station operators involved were monitoring the affected perimeter zone, a judgmental error resulted in the failure to follow an explicit procedure.

To ensure future security compensatory measures are maintained, the effected security officers were reprimanded regarding their actions and all security crews were briefed by security supervision on the details of this event. The implementation of proper compensatory actions will also be made a priority issue during future performance testing of all security operators. Security management has been directed to provide close monitoring of procedure adherence by the security force to ensure this event is, in fact, an isolated occurrence.

In closing, the Security Department at Cooper Nuclear Station has maintained a noteworthy performance standard and our expectations will continue to ensure that any concerns or inadequacies are appropriately and expeditiously corrected.

Sincerely,

  
G. R. Horn  
Vice-President,  
Nuclear

GRH:rdw

cc: NRC Resident Inspector

94-1164

IE-04  
1/0