

CP&L

Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
POST OFFICE BOX 790
HARTSVILLE, SOUTH CAROLINA 29550

Robinson File No: 13510C

Serial: RSEP/82-1086

Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
LICENSEE EVENT UPDATE REPORT 80-027, REVISION 1

82 OCT 15 A10:43


USNRC REGION II
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the enclosed Licensee Event Update Report is submitted.

The original report, December 5, 1980, described the failure of a relay in the Reactor Protection System and referenced previous reports of the same conditions. This revision contains a complete description of the event with new information indicated by a vertical bar in the right hand margin. This report, therefore, supersedes and should replace all copies of the original Licensee Event Report.

Very truly yours,



R. B. Starkey, Jr.
General Manager
H. B. Robinson SEG Plant

HTC/bs

Enclosure

cc: R. A. Hartfield (3)
R. C. DeYoung (30)

OFFICIAL COPY

IE 22

8210170240 821011
PDR ADOCK 05000261
S PDR