



October 7, 1982

Log No. K82-1454
File: RR 2 (NP-33-82-51)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 82-046
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: September 8, 1982

Enclosed are three copies of Licensee Event Report 82-046 with a supplemental information sheet which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/kl

enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Tom Peebles
NRC Resident Inspector
Encl: 1 copy

8210190254 821007
PDR ADDCK 05000348
S PDR

OCT 12 1982

vt 22