



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

October 12, 1982

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-42

Crack in "A" Recirculation System Riser
Manifold End Cap

The License Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.1.c since it represents abnormal degradation of reactor coolant pressure boundary components.

David Musolf
Manager of Nuclear Support Services

DMM/bd

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman