

DMB

Docket No. 50-346
License No. NPF-3
Serial No. 1-300
October 4, 1982

PRINCIPAL STAFF			
✓ RA	1100	OI	
D/RA		ENF	
A/RA		SP	
✓ DE&P		PAO	
DE&OS		SLO	
DE&TP			
OL		FILE	1100



RICHARD P. CROUSE
Vice President
Nuclear
(419) 259-5221

Mr. James G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

This letter is submitted to satisfy Technical Specification 4.4.5.5.a which requires Toledo Edison to report to the Commission the number of tubes plugged in each steam generator following each inservice inspection of steam generator tubes.

The following tubes have been plugged in the Davis-Besse Unit #1 steam generators:

<u>DATE</u>	<u>STEAM GENERATOR 1-1</u>	<u>STEAM GENERATOR 1-2</u>
April 1981	None	Row 47, Tube 1 Row 48, Tube 1
August 1982	Row 54, Tube 127 Row 61, Tube 126 Row 69, Tube 130	Row 40, Tube 1 Row 46, Tube 1 Row 83, Tube 130 Row 94, Tube 129

Yours truly,

RPCrouse

RPC/CTD

jc e/2

cc: A. DeAgazio - NRR
DB-1 NRC Resident Inspector

8210190303 821004
PDR ADOCK 05000341
PDR

OCT 7 1982

1E28