

GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704
AREA CODE 713 838-6631



October 7, 1982

RBG- 13,492

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-65

On August 6, 1982, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning cracking and spalling of surface concrete around penetrations in the River Bend Station Drywell Wall (DR-65). GSU has not completed its investigation at this time. An interim or final status report will be provided by December 3, 1982.

Sincerely,

A handwritten signature in cursive script, appearing to read "William J. Booker".

for J. E. Booker
Manager-Engineering & Licensing
River Bend Nuclear Group

JEB/^JRJK/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (RRI)

BE10190367 821007
PDR ADOCK 05000458
S PDR

IR27