## LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [1] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)	
1 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58	
CON'T  O 1 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80	
DURING OPERATING CONDITION 4, APPROXIMATELY 3.5 HOURS FOLLOWING AN AUTOMA	
TIC SHUTDOWN, THE HIGH PRESSURE SERVICE WATER (HPSW) CONTAINMENT ISOLATIO	
N VALVE WENT CLOSED. THE VALVE CLOSURE ISOLATED THE CONTAINMENT BUILDING	_
BASEMENT HOSE STATION FROM ITS WATER SUPPLY. NO ADVERSE CONSEQUENCES.	
06	
07	
7 8 9  SYSTEM CAUSE CAUSE  COMP. VALVE	80
CODE SUBCODE S	
COMPONENT   COMP	ER 5 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  AN AIR LEAK AT A FITTING ON THE VALVE OPERATOR AIR SUPPLY LINE CAUSED THE	
VALVE, WHICH REQUIRES AIR TO OPEN, TO GO CLOSED. THE VALVE WAS REOPENED	
IN LESS THAN ONE HOUR. THE AIR SUPPLY LINE FITTING WAS TIGHTENED.	
13	
7 8 9	80
FACILITY STATUS 30 OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA SUPERVISOR OBJERVATION 32	80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35  1 6 Z 33 Z 34 NA  NA  NA  NA  NA  NA  NA  NA	80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  1 7 8 9 PERSONNEL INJURIES  PERSONNEL INJURIES  13 PERSONNEL INJURIES	80
1 8 0 0 0 0 0 NA  NUMBER OF DESCRIPTION (41)  NA  1 8 9 11 12	80
LOSS OF OR DAMAGE TO FACILITY (43)  TYPE DE CRIPTION  1 9 Z 42 NA  PDR ADOCK 05000409  PDR	80
PUBLICITY ISSUED DESCRIPTION 45  NRC USE ONLY  NRC USE ONLY  RC USE ONLY  RC USE ONLY  RC USE ONLY	13.62
NAME OF PREPARER L. S. GOODMAN PHONE: 608-689-2331	0 0