



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

October 8, 1982

Mr. James G. Keppler, Regional Administrator
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: LaSalle County Station - Units 1 and 2
10 CFR 50.55(e), #82-10
RCIC Underground Piping - Revised Final Report
NRC Docket Nos. 50-373/374

Reference (a): C. W. Schroeder letter to J. G. Keppler
dated June 29, 1982

Dear Mr. Keppler:

Reference (a) stated that replacement piping for Unit #1 will be completed by October 15, 1982. At the present time the piping is complete except for the tie to Unit #1 RCIC system inside the building. This work requires at least a six (6) day outage.

The work will be completed during the first available outage of six (6) days or greater. This delay should not present any safety concerns as the existing Unit #1 piping has successfully passed required tests. Commonwealth Edison decided to replace the Unit #1 piping in order to avoid the cracking problem exhibited by the Unit #2 piping.

If there are any further questions in this matter, please contact this office.

Very truly yours,

C. W. Schroeder
Nuclear Licensing Administrator

cc: NRC Resident - LSCS
Director of Inspection and
Enforcement - Washington, DC

8210190606 821008
PDR ADGCK 05000373
S PDR

OCT 12 1982
LE 27