



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

October 8, 1982


Regional Administrator  
Region III  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-306 License No. DPR-60

Degraded Voltage Relays on Unit 2 Safeguards Buses  
Found Out of Specification

The License Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2(a) since it represents instrument settings outside of the allowable range. Redundant logic components would have prevented improper operation.



David Musolf  
Manager of Nuclear Support Services

DMM/bd

cc: NRC Document Control Desk (1)  
NRC Resident Inspector  
MPCA  
Attn: J W Ferman

Attachment

8210190726 821008  
PDR ADDCK 05000306  
S PDR

OCT 12 1982

led2