

Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-373

Docket No. 50-374

As a result of the inspection conducted on August 2-31, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

10 CFR 55.3(a) states, "No person may perform the function of an operator as defined in this part except as authorized by a license issued by the Commission."

10 CFR 55.4(d) and (f) define the function of an operator as manipulation of a control of the facility which directly affects the reactivity or power level of the reactor.

10 CFR 55.9(b) states, "Nothing in this part shall be deemed to require a license for... An individual who manipulates the controls of a facility as part of his training to qualify for an operator license under this part under the direction and in the presence of a licensed operator or senior operator."


Contrary to the above, on August 18, 1982, an operator trainee was observed moving control rods during a startup of Unit 1 without direction from or in the presence of a licensed operator or Senior operator.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

OCT 7 1982

Dated



J. F. Streeter, Chief  
Projects Branch 2