

Appendix

NOTICE OF VIOLATION

Monsanto

License No. 24-01113-20

As a result of the inspection conducted on October 1, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition No. 13.A(1) requires that each sealed source be tested for leakage and/or contamination at intervals not to exceed three years.

Contrary to the above, sealed cesium-137 sources in you Ohmart nuclear gauges have not been leak tested in at least six years.

This is a Severity Level IV violation (Supplement VI).


2. License Condition No. 6 states the specific byproduct materials that you are authorized to possess under this license. Our letter, dated July 24, 1979 (signed by Nathan Bassin, License Management Branch) states, "Please note that phosphorus-32 for dental abrasion studies has not been included in your license."

Contrary to the above, phosphorus-32 for dental abrasion studies was possessed and used from July 1979 until July 1980 while not authorized by your license.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

10-12-82
Dated


D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1