

P.O. Box 270 • Hartford, Connecticut 06101 • (203) 666-6911 X 5489

BWROG-8257

October 4, 1982

U. S. Nuclear Regulatory Commission  
Division of Licensing  
Office of Nuclear Reactor Regulation  
Washington, DC 20555

Attention: Darrell G. Eisenhut, Director

Gentlemen:


Subject: Errata to BWR Emergency Procedure Guidelines

Reference: NEDO-24934, Emergency Procedure Guidelines,  
BWR/1-6, Revision 2 (prepublication form)

Enclosed for your review are errata to the reference document, a copy of which was submitted to you on June 1, 1982. These changes and corrections are provided in the form of replacement pages for that document. None of these errata make a significant change to the BWR Emergency Procedure Guidelines, and each was discussed with members of your staff in our meeting on September 23, 1982.

The enclosed material has been endorsed by a substantial number of the members of the BWR Owners' Group; however, it should not be interpreted as a commitment of any individual member to a specific course of action. Each member must formally endorse the BWR Owners' Group position in order for that position to become the member's position.

Very truly yours,



T. J. Dente, Chairman  
BWR Owners' Group

TJD:STR:jmh  
Enc.

cc: BWR Owners' Group  
J. F. Schil'ar (GE)  
S. J. Stark (GE)  
M. W. Hodges (NRC)  
D. L. Ziemann (NRC)

*0002*