

RECEIVED
10 PM 11:26

Southern California Edison Company

SCE

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY

STATION MANAGER

October 15, 1982

TELEPHONE
(714) 492-7700

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361
Interim Follow-Up Reports
Licensee Event Reports Nos. 82-094 and 82-103
San Onofre Nuclear Generating Station, Unit 2


Reference: Letters, H. B. Ray (SCE) to R. H. Engelken (NRC), dated
September 7, 1982 and September 23, 1982

In the referenced letters, which described reportable conditions involving Limiting Condition for Operation (LCO) 3.6.3 associated with containment isolation valves, we stated that follow-up reports and revised LER's would be provided by October 15, 1982. These follow-up reports were to address the conclusions made from an engineering investigation involving maintenance and/or adjustments of limit/torque switches. It has been determined that additional evaluation and careful formulation of our corrective actions will require more time than originally anticipated.

Accordingly, the follow-up reports, identified in the referenced letters, will be provided by November 30, 1982, instead of October 15, 1982.

If you have any questions or concerns regarding this deferment, please contact me.

Sincerely,



cc: A. E. Chaffee (USNRC Resident Inspector, San Onofre Unit 2)

8210250207 821015
PDR ADOCK 05000361
S PDR

IE-22
82-356