



**LOUISIANA**  
POWER & LIGHT


142 DELARONDE STREET  
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

L. V. MAURIN  
Vice President  
Nuclear Operations

October 15, 1982

W3I82-0074  
Q-3-A35.07.23

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency Report No. 23  
"Defective Valve Actuators (Fisher Controls)"  
Seventh Interim Report

REFERENCES: (1) LP&L Letter W3K81-0127 Dated March 16, 1981  
(2) LP&L Letter W3K82-0290 Dated May 20, 1982

Dear Mr. Collins:

At the present time, the corrective action as described in reference 1 is still in progress. Rework of the valves is being performed under the technical supervision of the Technical Sales, Inc. site representative. A final report will, therefore, be transmitted by January 7, 1983.

Very truly yours,

*L. V. Maurin*  
L. V. Maurin

LVM/MAL:keh

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

IE27

8210250254 821015  
PDR ADOCK 05000382  
S PDR