



**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

September 22, 1982

DJS Ltr. #82-991

James G. Keppler, Regional Administrator  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Updated Reportable Occurrence Report #82-29/01X-1, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1(a), failure of the reactor protection system or other systems subject to limiting safety system settings to initiate the required protective function by the time a monitored parameter reaches the setpoint specified as the limiting safety system setting in the technical specifications or failure to complete the required protective function. The results of the vendor's review of this incident are addressed.

D. J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Management Branch  
File/NRC

8210250306 5

OCT 18 1982

PE 22