


TEXAS UTILITIES GENERATING COMPANY

2001 BRYAN TOWER DALLAS, TEXAS 75201-3050

R. J. GARY
EXECUTIVE VICE PRESIDENT
AND GENERAL MANAGER



October 12, 1982
TXX-3580

Mr. G. L. Madsen, Chief
Reactor Project Branch 1
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

Docket Nos. 50-445
50-446

COMANCHE PEAK STEAM ELECTRIC STATION
DEFECTIVE LIMITORQUE PINION KEYS
FILE NO.: 10110

Dear Mr. Madsen:

On August 18, 1982, we verbally informed your Mr. Tom Westerman of a deficiency regarding defective pinion keys in Limatorque motor operators. We have submitted an interim report logged TXX-3569 dated September 14, 1982.

We have completed our investigation and concluded that the matter is not reportable under 10CFR50.55(e). Records supporting this determination are available for your Inspector's review at the CPSES site.

Very truly yours,

R. J. Gary
for R. J. Gary

RJG:eaq

cc: NRC Region IV - (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, DC 20555

IE 27

8210250338 5