(12.81) 10 CFR 2.201	SAFETY IN	ISPECTION		
OHIO DIVISION of GEOLOG BLOG B, FOUNTAIN SQUI COLUMBUS, OHIO 43224	ARE SURVEY	Office of Region I	clear Regulatory Com f Enspection & Enfor	
3 DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION	
	34-14180	-02	4-11-83	
Licensee:				
The inspection was an examination of the activitie Regulatory Commission's (NRC) rules and regulationand representative records, interviews, with person 1. Within the scope of this inspection, no violation	ons and the conditions of your nnel, and observations by the ir	license. The inspecti	on consisted of selective examina	tions of procedures
The inspector also verified the steps you hat those actions at this time.  3. During this inspection certain of your activities.				rther questions on
THIS IS A NOTICE OF VIOLATION which	th is required to be posted in a	ccordance with 10 CF	R 19.11.	
A			was not properly posted to	ndicate the presence
of a			. 10 CFR 20.203(b),	c), (d), (e) or 34.42.
B. Containers located in		03(f)(1), or (f)(2).		were not properly
			of sealed sources were not per	formed at the proper
frequencies. 10 CFR		License	Condition Number	
D. Records of		License Condition N		properly maintained.
			united	
E. Documents were not properly posted or	otherwise made available. 10	CFR 19.11.		
F. Reports or notifications of			were not	made in accordance
with 10 CFR	OI	r License Condition N	umber	
Н				
J				
Пк		LE DI	HQ File (	Popy
I hereby state that within 30 days the actions describe statement of corrective actions as made in accordance.				
This statement of corrective actions is made in accidente NRC.  8304260199 830411  NMS LIC30  34-14180-02 PDF		Stan	ley R. Lazuk	4/11/83
SIGNATURE - LICENSEE	DATE	SIGNATU	RE- NRC INSPECTOR	DATE