

October 19, 1982

Mr. James G. Keppler
Regional Administrator
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Sir:

Reportable Occurrence Report #82-114/017-0 Docket #050-373 is being submitted to your office in accordance with LaSalle County Nuclear Power Station Technical Specification 6.6.B.1.(i), performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the SAR or technical specifications bases, or discovery during plant life of conditions not specifically considered in the SAR or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition.

G. J. Diederich Superintendent LaSalle County Station

GJD/GW/1rw

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC Document Management Branch
Inpo-Records Center
File/NRC

OCT 2 0 1982

B210260115 B21019 PDR ADOCK 05000373 S PDR IEZZ