

50-400, 40L

USNRC REGION II
ATLANTA, GEORGIA

CP&L

Carolina Power & Light Company

83 APR 21 AIO: b3 O. Box 101, New Hill, N. C. 27562
April 18, 1983

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest (Suite 3100)
Atlanta, Georgia 30303

NRC-61

CAROLINA POWER & LIGHT COMPANY
SHEARON HARRIS NUCLEAR POWER PLANT
1986-90 - 900,000 KW - UNITS 1 & 2
WELDING DEFICIENCIES IN THE MAIN STEAM/FEEDWATER
SUPPORT FRAMES, ITEM 121


Dear Mr. O'Reilly:

On March 18, 1983, Mr. N. J. Chiangi notified the NRC (Mr. A. Hardin) of a potentially reportable item per the provisions of 10CFR50.55(e) and 10CFR, Part 21. Mr. Hardin was informed that two Bergen-Paterson Main Steam/Feedwater Support Frames received at the site potentially have weld deficiencies similar to those found in another frame fabricated by the same sub-vendor.

These frames are currently being inspected at the site to assure that similar deficiencies are not present. This evaluation is not expected to be complete until June 1, 1983. For this reason, we request an extension until June 17, 1983 for submitting a report on the reportability of this item.

Thank you for your consideration in this matter.

Yours very truly,



R. M. Parsons
Project General Manager
Shearon Harris Nuclear Power Plant

RMP/sh

cc: Mr. G. Maxwell (NRC-SHNPP)
Mr. V. Stello (NRC)

IE19

OFFICIAL COPY

IE29

8304260304 830418
PDR ADOCK 05000400
S PDR