



Carolina Power & Light Company

P. O. Box 101, New Hill, North Carolina 27562
April 18, 1983

FILE: SH N-2/18
Item 114

MQAH 83-37

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT, UNITS 1 AND 2
DOCKET NOS. 50-400, 50-401
MATERIAL FOR ANCHOR BOLTS AND NUTS FOR DIESEL GENERATOR
NOT TYPE SPECIFIED BY DESIGN

Dear Mr. O'Reilly:

This is to confirm the April 15, 1983 telephone conversation between Mr. N. J. Chiangi and Mr. A. Hardin. Mr. Hardin was informed that the January 17, 1983 potentially reportable item, pertaining to incorrect material (anchor bolts and nuts) supplied for the Emergency Diesel Generator by Transamerica Delaval, has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e) and 10CFR, Part 21.

Thank you for your consideration in this matter.

Yours very truly,

N. J. Chiangi - Manager
Quality Assurance/Quality Control
Harris Plant

NJC/mt

cc: Mr. G. Maxwell
Mr. V. Stello

IE19

8304260427 830418
PDR ADOCK 05000400
S PDR

OFFICIAL COPY

~~IE27~~