



**Florida  
Power**  
CORPORATION

April 8, 1983  
3F-0483-09

83 APR 21 AID: 13  
NO RECORD  
RECEIVED

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement  
101 Marietta Street N.W., Suite 2900  
Atlanta, GA 30303

Subject: Crystal River Unit 3  
Docket No. 50-302  
Operating License No. DPR-72  
Licensee Event Report No. 83-010, Rev. 1

Dear Mr. O'Reilly:

Enclosed in Licensee Event Report 83-010, Rev. 1 and the attached supplementary information sheet, which are submitted in accordance with Technical Specification 6.9.1.9.b.

This report documents the inoperability of the Meteorological Monitoring instrumentation for the period between (February 26 and March 15). It should be noted the Control Room log book indicates that the Meteorological instrumentation was inoperable from February 26 till March 9 and then again from March 10 till March 15.

Sincerely,

G. R. Westafer  
Manager,  
Nuclear Licensing and Fuel Management

PGH/caw

Enclosure

cc: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8304260480 830408  
PDR ADDCK 05000302  
S PDR

OFFICIAL COPY  
TE 22