## Arizona Fublic Service Company

P.O. BOX 21686 . PHOENIX, ARIZONA 85036

April 15, 1983 ANPP-23515-RQT/BSK



U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief Reactor Projects Branch 1

Subject: Time Extension For Report - DER 82-2

A 50.55(e) Potentially Reportable Deficiency Relating to Valve Operators Accidentally Interchanged By Posi-Seal On

Inside and Outside Containment Valves For Unit 1

File: 83-019-026; D.4.33.2

Reference: (A) Telephone Conversation between A. D'Angelo and G. Duckworth on January 25, 1983

(B) ANPP-23070, dated February 23, 1933 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by April 20, 1983.

Due to the extensive evaluation required, it is now expected that this information will be finalized by June 16, 1983, when a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr. APS Vice President

Nuclear Projects Management

ANPP Project Director

EEVB/RQT:db cc: See Page 2

1E27

Mr. D. M. Sternberg ANPP-23515-RQT/BSK April 15, 1983 Page 2

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr. G. C. Andognini J. A. Roedel

D. B. Fasnacht A. C. Rogers

B. S. Kaplan

W. E. Ide

J. Vorees

J. R. Bynum

P. P. Klute/D. D. Green

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

R. M. Grant

D. R. Hawkinson

L. E. Vorderbrueggen

G. A. Fiorelli

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339