SAFEGUARDS INFORMATION

MAR 1 1983

Florida Power and Light Company ATTN: Dr. R. E. Uhrig, Vice President Advanced Systems and Technology P. O. Box 14000 Juno Beach, FL 33408

Gentlemen:

SUBJECT: REPORT NO. 50-335/83-01:EA 83-08

This refers to the special safeguards inspection conducted by the Region II staff on January 6, 1983, of activities authorized by NRC License No. DPR-67 at St. Lucie 1 and to the discussions of our findings held with Mr. C. M. Wethy, Plant Manager, at the conclusion of the inspection.

The purpose of this inspection was to evaluate the significance of a security event reported to the NRC on January 4, 1983. The findings of this special inspection, which are documented in the enclosed report, revealed that a breach of vital area security resulted from a violation of regulatory requirements. The violation and related NRC concerns were further discussed during an Enforcement Conference held at St. Lucie on February 23, 1983.

The violation identified in the enclosed Notice of Violation regarding failure to provide positive access control to a vital area at an operational facility is normally categorized as a Severity Level III violation (10 CFR 2. Appendix C, Supplement III). However, in weighing the safety significance of the event, we have determined that the violation is appropriately categorized as Severity Level IV. You are required to respond to the Notice and follow the instructions therein. Elements to be included in your response are delineated in the Notice. Details of activities involving safeguards information are exempt from disclosure in accordance with 10 CFR 73.21. Therefore, your response should be incorporated in a separate paper and referenced in your reply.

In addition to the need for corrective action regarding these specific items of noncompliance, we are concerned about the continued adequacy of your intrusion detection system until the new system becomes fully operational on Unit 1. Consequently in your reply you should describe in particular those actions taken or planned to assure the effectiveness of the present intrusion detection system.

The material enclosed herewith contains Safequards Information as defined by 10 CFR 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material, with the exception of the report cover page which is an inspection summary, will not be placed in the Public Document Room.

8304280152 830301 PDR ADOCK 05000335

ENCLOSURE CONTAINS UPON SEPARATION THIS PAGE IS DECONTROLLED.

SAFEGUARDS INFORMATION.

The responses directed by this letter and the enclosures are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

R. C. Lewis, Director Division of Project and Resident Programs

Enclosures:

- Inspection Report No. 50-335/83-01 (Safeguards Information)
- 2. Notice of Violation
 (Safeguards Information)

cc w/encls: C. M. Wethy, Plant Manager Nat Weems, QA Construction Manager

bcc w/encls: IE File NMSS/SGPL NRR/DL/SSPB

bcc w/Inspection Summary Document Management Branch NRC Resident Inspector State of Florida

CPerny:my 01/17/83 RII CAlderson 01/95/83 DRMcGuire 01/17/83 RI RCLevis 01/2/83 JPStohr 01/7/83

RII RDMartin 01/83 CAJulian 01//8/83

RII CX for HCDance 01//8/83

D.R. McCruie to ENCLOSURE CONTAINS
D. Rosano IE: EN SORBEMBATARDS INFORMATION.
1/39/83
UPON SEPARATION THIS
PAGE IS DECONTROLLED.