

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T REPORT SOURCE L 0 5 0 0 0 3 1 6 7 0 3 2 3 8 3 8 0 4 2 2 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 DURING NORMAL OPERATION, FIRE DOOR #386 WAS FOUND UNLATCHED. THIS CONSTITUTED AN
0 3 INOPERABLE PENETRATION FIRE BARRIER, NONCONSERVATIVE WITH RESPECT TO T.S. 3.7.10.
0 4 THE ACTION STATEMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.
0 5 THERE ARE NO PREVIOUS OCCURENCES OF A SIMILAR NATURE ON THIS DOOR.

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
A B E B X X X X X X Z Z
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 3 0 3 7 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPR-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
E Z Z Z 0 0 0 0 N N A X 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 FIRE DOOR #386 WOULD NOT LATCH DUE TO INSUFFICIENT CLOSER MECHANISM FORCE.
1 1 THE DOOR CLOSER MECHANISM WAS ADJUSTED AND THE DOOR OPERATED SATISFACTORILY.

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 1 0 0 NA B R. P. TECH OBSERVATION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z Z NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 Z NA
PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 NA
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z NA
PUBLICITY ISSUED DESCRIPTION
N NA

8305020171 830422
PDR ADOCK 05000316
S PDR

D. ROBINSON

616-465-5901

NAME OF PREPARER

PHONE: