



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215/770-5151

November 3, 1982

Mr. R.C. Haynes  
Director, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 82-036/01P-0  
ER 100450 FILE 841-23  
PLA- 1380

Docket No. 50-387  
License No. NPF-14

Dear Mr. Haynes:

This transmission confirms the telephone report of November 1, 1982, by D.G. Mitchell to E. McCabe of your staff, regarding the "as found" instrument settings on the High Pressure Coolant Injection isolation high steam line delta pressure detection. The settings were above the allowable value, thus preventing for this function, the isolation valves from isolating on a steam line break at the analysis assumed value.

This condition is considered reportable in accordance with Technical Specification 6.9.1.8.e.

H.W. Keiser  
Superintendent of Plant-Susquehanna

DGM/cw

cc: Richard C. DeYoung - Director, Office of Inspection & Enforcement  
Norman H. Haller - Director, Office of Management and Program Control  
U.S.N.R.C. - Resident Inspector, Susquehanna SES

8211180286 821103  
PDR ADOCK 05000387  
S PDR

IE29