



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JUN 14 1994

Docket: 030-05933
License: 35-11114-01

Capital X-Ray Services, Inc.
ATTN: George Johnson
Radiation Safety Officer
2133 South 49th West Avenue
Tulsa, Oklahoma 74107

SUBJECT: NRC INSPECTION REPORT 030-05933/94-01

This refers to the routine, unannounced inspection conducted by Mr. Richard A. Leonardi, Jr., of this office on June 1, 1994. The inspection included a review of activities authorized by Byproduct Materials License 35-11114-01. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.

The inspector determined that Capital X-Ray Services had utilized three 8-hour work shifts with a total of 19 full-time radiographers to meet its scheduled workload. He further noted that you possess and use a ytterbium-169 sealed source for radiography, and that portable survey instruments, pocket dosimeters, and alarm ratemeters were calibrated with a cesium-137 sealed source.

The inspector's review of randomly selected records indicated that the radiation safety officer appeared effective in maintaining an appropriate level of program oversight and had effectively implemented adequate control over licensed activities.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

200003

9406210003 940614
PDR ADOCK U3005933
C PDR


JEON 10


Capital X-Ray Services, Inc.

-2-

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,



 Charles L. Cain, Acting Chief
Nuclear Materials Inspection Branch

cc:
Oklahoma Radiation Control Program Director

bcc:
DMB - Original (IE-07)
LJCallan
SJCcollins
RAScarano
DWeiss, OC/LFDCB (T-9E10)
*WLFisher
*CLCain
*FAWenslawski, WCFO
*RALeonardi
*NMIB
*MIS System
*RIV Files (2)

*W/IFS Form

RIV:NMIB <i>RA7</i>	AC:NMIB <i>[Signature]</i>			
RALeonardi	CLCain <i>[Signature]</i>			
06/13/94	06/13/94			

bcc:

DMB - Original (IE-07)

LJCallan

SJCollins

RAScarano

DWeiss, OC/LFDCB (T-9E10)

*WLFisher

*CLCain

*FAWenslawski, WCFO

*RALeonardi

*NMIB

*MIS System

*RIV Files (2)

*W/IFS Form

RIV:NMIB <i>RA7</i>	AC:NMIB <i>[Signature]</i>			
RALeonardi	CLCain <i>[Signature]</i>			
06/13/94	06/13/94			