

April 26, 1983

Mr. J. G. Keppler, Regional Administrator Office of Inspection and Enforcement, Region III U. S. NUCLEAR REGULATORY COMMISSION 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET 50-301 LICENSEE EVENT REPORT 83-002/01T-0 POINT BEACH NUCLEAR PLANT, UNIT 2

Enclosed is Licensee Event Report 83-002/01T-0

(a 14-day follow-up report) which provides a description of an event reportable according to Technical Specification 15.6.9.2.A.3, "Abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment."

Very truly yours,

Vice President

C. W. Fay

Enclosure

Copy to NRC Resident Inspector

B305030275 E30426 PDR ADDCK 05000301 S PDR Trys