



Nuclear Division P.O. Box 4 Shippingport, PA 15077-0004

> April 13, 1983 ND1SS1:801

Beaver Valley Power Station, Unit No. 1 Docket No. 50334, License No. DPR66 LER 79-023/03X-1

Regional Administrator
United States Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Sir:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Updated Licensee Event Report is submitted:

LER 79-023/03X-1, Technical Specification 6.9.1.9.b, No. 1 Diesel Generator output breaker failed to close.

Very truly yours,

Wm. S. Lacey

Superintendent

Attachment

Mr. R. C. Haynes April 13, 1983 NDISS1:801 Page 2

cc: Director Of Management & Program Analysis United States Nuclear Regulatory Commission Washington, D. C. 20555

J. Hultz, Ohio Edison

Director, Office of Inspection and Enforcement Headquarters United States Nuclear Regulatory Commission Washington, D. C. 20555

Mr. Peter Tam, BVPS Licensing Project Manager United States Nuclear Regulatory Commission Washington, D. C. 20555

W. M. Troskoski, Nuclear Regulatory Commission, BVPS Site Inspector

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator, Toledo Edison

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Arthur Alford, Stone & Webster/Boston