

APPENDIX A

NOTICE OF VIOLATION

Long Island Lighting Company
Shoreham Nuclear Power Station

Docket No. 50-322
License No. CPPR-95

As a result of the inspection conducted on September 9 - October 13, 1982, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 9, 1982 (47 FR 9987), the following violation was identified:

10 CFR 50, Appendix B, Criterion VI, FSAR paragraph 17.1.6A, and the LILCO Engineering Quality Assurance Manual paragraphs 6.3.2 and 6.3.4 require that measures be established to control the issuance of drawings, including the prompt incorporation of changes and a review for adequacy before release.

Engineering and Design Coordination Report (E&DCR) No. F-6085B, dated June 20, 1979 indicated wiring changes to be made on drawings 1.61-154 and 1.61-156.

Contrary to the above, measures did not ensure the prompt incorporation of changes into drawings in that Revision C to drawings 1.61-154 and 1.61-156, issued in 1981, indicated that E&DCR No. F-6085B had been incorporated, when in fact the wiring changes of the E&DCR were not incorporated into these drawings.

This is a Severity Level V Violation (Supplement II.E).

Pursuant to the provisions of 10 CFR 2.201, Long Island Lighting Company is hereby required to submit to this office within thirty days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.