(7-91) 10 CFR 2.201	SAFETY	INSPECTION			
			Page 1	of _	
RASINTION Sufety CA		475 Al	ON I UCLEAR REGULATORY COMMISSION LENDALE ROAD OF PRUSSIA PA 19406-1415		
3. DOCKET NUMBER(S) 030-00458 030-31783	4. LICENSE NUMBER(8 37 - 0069 37 - 0069	7-102	5. DATE OF INSPECTION		
LICENSEE: The inspection was an examination of the act Regulatory Commission (NRC) rules and regulatory conductions and representative records, interviolations.	ulations and the condition	s of your license. The in	spection consisted of selective examinations	s of	
Within the scope of this inspection.	no violations were observ	ed.			
The inspector also verified the steps questions on those actions at this till.		of the violations identified	during the last inspection. We have no furt	ther	
During this inspection certain of you NOTICE OF VIOLATION, which is re			in violation of NRC requirements. This form 3.11.	is a	
A			was not properly posted to		
indicate the presence of a	indicate the presence of a		10 CFR 20.203(b),(c),(d),(e) or 34.42.		
8.			of sealed sources were not		
performed at the proper frequency	uencies 10 CFR	or Licens	e Condition Number		
C. Records of			were not properly maintaine	ed.	
10 CFR or License Condition Number		lumber			
D. Documents were not properly	posted or otherwise made	de available. 10 CFR 19.	α,		
E. Reports or notification of	Reports or notification of		were not made in accordance with		
10 CFR	or License Condition N	lumber			
F					
C	03000458 PDR		110		
DESIGNATED ORIGIN	AL RET	TURN ORIGINAL	IE:	07	
Certified by: Mc	anco	REGION I	May.		
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.	described by me to the	Inspector will be taken to hithe requirements of 10	correct the violations identified in the items CFR 2.201. No further response will be sub-	checked	
21446	Dal	CONTRACTOR MASSING	SUCCESSOR BATE		

NRC FORM 591 Part 1 (7-91)