

TMI RA

December 6, 1979

Docket No. 50-320

Metropolitan Edison Company  
Att: Mr. R. F. Wilson, Director  
TMI-2 Recovery, Acting  
P.O. Box 480  
Middletown, Pennsylvania 17057

Dear Mr. Wilson:

SUBJECT: GPU INTER-OFFICE LETTER, TMI-II-R-1152, CHANGE IN BWST  
MINIMUM INVENTORY, DATED NOVEMBER 26, 1979

We have received the GPU Inter-Office letter, TMI-II-R-1152 that provides an evaluation for a change in BWST minimum inventory. Our comments are enclosed. In order to expedite our review and approval of the subject change we suggest that you incorporate the resolution to our comments in your forthcoming formal letter to NRC addressing the same subject.

Sincerely,

J. T. Collins, Deputy Director  
TMI Support

Attachment:  
As stated

cc: w/attachment  
B. Beebe  
L. Harding  
B. Elam  
D. Brinkman  
M. Greenberg  
A. Ignatonis  
J. G. Herbein, Vice President Nuclear Operations  
E. G. Wallace, Manager Licensing  
G. P. Miller, Manager Support Services and Logistics  
J. B. Logan, Superintendent Unit 2  
G. A. Kunder, Unit 2 Superintendent - Technical Support  
J. J. Colitz, Manager Plant Engineering

Distribution  
SEP r/f  
PSB r/f  
TMI r/f  
NRR r/f  
CENTRAL FILE  
NRC PDR  
LOCAL PDR  
JTCOLLINS  
RHVOLLMER  
ORIGINATOR

8212010379 791206  
PDR ADOCK 05000320  
P PDR

TMI  
*A. Ignatonis*  
A Ignatonis/ws

TMI  
*M. Greenberg*  
M Greenberg

TMI  
*J. T. Collins*  
J. Collins

12/6/79

12/6/79

12/6/79

821150440

Metropolitan Edison Company  
Mr. R. F. Wilson

2

December 6, 1979

cc: Continued

I. R. Finfrock, Jr.

R. W. Conrad

G. F. Trowbridge, Esquire

J. B. Lieberman, Esquire

Ms. Mary V. Southard, Chairperson, Citizens for a Safe Environment

PROCEDURE COMMENT SHEET

Procedure Number/Title GPU INTER-OFFICE LETTER TMI-II-R-1152 / CHANGE IN BWST MIN. INVENTORY

Review Group NRR / NRC

Telephone Ext. 782 - 3971

Name/Date AL IGNATONIS 12-06-79

Section	Comment	Resolution	Accept	Reject	Reason
APPENDIX "A"	<p>IN DETERMINING THE MIN. BWST INVENTORY YOU SHOULD ALSO ACCOUNT FOR INSTRUMENT ERROR AND THE WORKING LEVEL.</p>				
	<p>THE INSTRUMENT ERROR SHOULD BE TAKEN TWICE. ONCE, TO ASSURE THAT BWST INITIALLY CONTAINS 100,000 gal OF WATER. AND, THE SECOND TIME TO ASSURE THAT 83,500 gal. HAS BEEN INJECTED.</p>				
	<p>FOR WORKING ALLOWANCE, I MEAN THE LEVEL NECESSARY TO PREVENT ALARMS DUE TO SMALL WATER LOSSES FROM THE TANK.</p>				
MAIN BODY OF LETTER	<p>LETTER STATES WHENEVER BWST CONTAINS LESS THAN 100,000 gal. BACKUP EQUIVALENT INVENTORY WILL BE AVAILABLE. IDENTIFY THE BACKUP STORAGE TANK(S) AND ITS TRANSFER PATH.</p>				

PROCEDURE COMMENT SHEET

Procedure Number/Title GPU INTER-OFFICE LETTER TMI-II-R-1152  
Review Group NRR/NRC Telephone Ext. \_\_\_\_\_  
Name/Date AL IGNATONIS 12-06-79

Section	Comment	Resolution	Accept	Reject	Reason
MAIN BODY OF LETTER	PROVIDE REASON(S) WHY THE MIN. BWST INVENTORY SHOULD REPRESENT THREE DAYS OF SUPPLY. IF THE REASON IS THAT THIS IS AN ADEQUATE TIME TO GET ADDITIONAL BORATED WATER THEN IT SHOULD BE ADRESSED.				