



November 24, 1982

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

121 Auxiliary Building Special Ventilation Failed DOP Test

The License Event Report for this occurrence is attached to this letter.

This event is reported in compliance with Technical Specification 6.7.B.2.(b) since it placed the plant in a degraded mode as permitted by limiting conditions of operations.

for David Musolf
Manager - Nuclear Support Services

DMM/SAF/js

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman

8212020311 821124
PDR ADOCK 05000282
S PDR

NOV 26 1982
FE 22