



# Nebraska Public Power District

COOPER NUCLEAR STATION  
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321  
TELEPHONE (402)825-3811  
FAX (402)825-5211

NSD940571  
June 16, 1994

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555

Subject: Completion of Actions Requested by NRC Bulletin 93-02, Supplement 1,  
Cooper Nuclear Station, NRC Docket 50-298, DPR-46

Reference: Letter from G. R. Horn (NPPD) to USNRC dated April 18, 1994,  
"Response to NRC Bulletin No. 93-02, Supplement 1"

Gentlemen:

NRC Bulletin 93-02, Supplement 1, requested licensees to take the appropriate actions to ensure reliability of the Emergency Core Cooling System (ECCS) in view of the information discussed in the bulletin supplement regarding the vulnerability of the ECCS suction strainers to clogging. Reference 1 provided the District's actions that would be taken to ensure the reliability of the ECCS regarding the vulnerability of the ECCS due to suction strainer clogging.

The Nebraska Public Power District (District) has completed the training to the appropriate personnel as committed to in its response (Reference 1). This notification fulfills the final reporting requirement specified in NRC Bulletin 93-02, Supplement 1. As instructed by the bulletin, this information is being provided under oath.

Please contact me if you have any questions or require any additional information.

G. R. Horn  
Vice President - Nuclear

GRH:tja/93-02sp1

cc: NRC Regional Administrator  
Region IV  
Arlington, TX

NRC Resident Inspector  
Cooper Nuclear Station

210103

9406220353 940616  
PDR ADDCK 05000298  
PDR

IE11  
110

