



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JUN 20 1994

Docket: 030-22309
License: 35-23195-01

Cardiology of Tulsa, Inc.
ATTN: Robert Okada, M.D.
Radiation Safety Officer
6585 South Yale, Suite 800
Tulsa, Oklahoma 74136

SUBJECT: NRC INSPECTION REPORT 030-22309/94-01 (NOTICE OF VIOLATION)

This refers to the routine, unannounced inspection conducted by Mr. Richard A. Leonardi, Jr., of this office on June 2, 1994. The inspection included a review of activities authorized by Byproduct Materials License 35-23195-01. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice).

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

The inspector determined that licensed materials were received, used, and disposed of in accordance with regulatory requirements and license conditions. He further observed that the Radiation Safety Officer (RSO) had focused sufficient attention to the radiation safety program and that although some tasks were delegated to other individuals, the results of these surveys, tests, and evaluations were given adequate review by the RSO to ensure that they had been properly completed.

One of the violations described in the enclosed Notice involved a failure to notify the NRC in writing when an authorized user discontinued performing

9406230017 940620
PDR ADDCK 03022309
C PDR

services under your NRC license. As discussed with your staff during the inspection, you must notify the NRC by letter within 30 days when an authorized user permanently discontinues performance of duties under the license.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this letter, please contact Charles L. Cain of my office at (817) 860-8186.

Sincerely,



Samuel J. Collins, Director
Division of Radiation Safety
and Safeguards

Enclosure:
Appendix - Notice of Violation

cc:
Oklahoma Radiation Control Program Director

bcc.

DMB - Original (IE-07)

LJCallan

SJCollins

RAScarano

DWeiss, OC/LFDCB (T-9E10)

*WLFisher

*CLCain

*FAWenslawski, WCFO

*RALeonardi

*NMIB

*MIS System

*RIV Files (2)

*W/IFS Form

RIV:NMIS <i>ROY</i>	AC:NMIS <i>WA</i>	DD:DRSS <i>WA</i>	D:DRSS <i>WA</i>	
RALeonardi	CLCain	RAScarano	SJCollins <i>WA</i>	
06/14/94	06/15/94	06/16/94	06/17/94	

200006

111