

APPENDIX A

Cooper Industries  
Cooper Energy Services  
Docket No. 99900317/82-01

NOTICE OF VIOLATION

As a result of the inspection conducted on September 20-24, 1982, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation, 10 CFR Part 21, the following violation was identified and categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987 (March 9, 1982):

Section 21.6 of Title 10, Part 21 of the Code of Federal Regulations, dated December 18, 1981, states in part:

Each individual, partnership, corporation or other entity subject to the regulations in this part, shall post current copies of the following documents in a conspicuous position on any premises, within the United States where the activities subject to this part are conducted (1) the regulations in this part, (2) Section 206 of the Energy Reorganization Act of 1974, and (3) procedures adopted pursuant to the regulations in this part.

If posting of the regulations in this part or the procedures adopted . . . is not practicable, the . . . firm subject to the regulations in this part may, in addition to posting section 206, post a notice which describes the regulations/procedures, including the name of the individual to whom reports may be made, and states where they may be examined.

Contrary to the above, posting of the regulation had not been accomplished, nor did the posted procedure (numerous locations) identify the location where 10 CFR Part 21 could be examined. Further, the copy of 10 CFR Part 21 on file in the Quality Control Office was not current; it was dated October 19, 1978.

This is a Severity Level V violation (Supplement VII).

8212070418 821112  
PDR GA999 EMVCDIN  
999005317 PDR