NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-82
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFOR	RMATION)
0 1 P A S E S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30	57 GAT E3 (5)
CON'T 0 1 REPORT L 6 0 5 0 0 0 3 8 7 7 1 0 3 1 8 2 8 1 1 2 9	8 2 9 ATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During the startup testing program, a Quality Assurance Reviewer det	ermined
0 3 that five safety related snubbers installed in the plant had not been	en
0 4 determined operable by performing the necessary surveillance. This	brought
o 5 to light the potential for the omission of other snubbers from the	listing
0 6 of identified snubbers. This is reportable per Technical Specificat	tion
0 7 6.9.1.9.c. No adverse consequences resulted.	
0 8	*0
SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE X X X 11	REVISION NO.
(17) REPORT 8 2	0 32 SOMBONENT (2)
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRO-4 SUBMITTED FORM SUB. SUPPLIER X 18 X 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 33 34 35 36 37 40 41 42 43	Z 9 9 9 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 1 0 Discrepancies in the safety related snubber list are the result of s	some
oversights in the turnover process between the AE and PP&L. PP&L had	
commenced verification of the list of safety related snubbers. Upon	n
completion of the list, surveillances will be run on any snubbers no	ot
1 4 previously done.	80
TACILITY STATUS , POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION DISCOVERY DESCRIPTION ASSURANCE Audit	32
ACTIVITY CONTENT AMOUNT OF ACTIVITY 35 LOCATION RELEASE 36)
7 8 9 10 11 44 45 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 0 0 0 (37) Z (38) n/a	**
7 8 9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION (41)	80
1 8 0 0 0 0 0 m/a	80
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION n/a	80
2 0 N 44 n/a	C USE ONLY
NAME OF PREPARER D.G. Mitchell PHONE: (717) 542-	2181 X524