



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

November 30, 1982

Mr. R.C. Haynes  
Director, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 82-043/01T-0  
ER 100450 FILE 841-23  
PLA- 1415

Docket No. 50-387  
License No. NPF-14

Dear Mr. Haynes:

Attached please find a copy of Licensee Event Report No. 82-043/01T-0. This event was determined to be reportable per Technical Specification 6.9.1.8.1, in that it has been determined that the failure of a single component could defeat the overload detection and protection devices for the containment penetration carrying power cables for the reactor recirculation pumps.

Additionally, please note that the letter confirming the telephone notification of this occurrence (PLA-1404, dated 11/18/82) should carry the LER number 82-043/01P-0.

H.W. Keiser  
Superintendent of Plant-Susquehanna

LAK/cw

cc: A. Schwencer  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

G. Rhoads  
Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 52  
Shickshinny, PA 18655

IE22