| 12-8 M | LICENSEE EVENT REPORT | APPROVED BY 0 3150-0011 EXPIREL 4-30-82 |
|---|--|--|
| CONTROL BLOCK: | PLEASE PRINT OR TYPE ALL | REQUIRED INFORMATION) |
| DI PASES 12 | 0 0 - 0 0 0 0 0 - 0 0 3 4 1 15 LICENSE NUMBER 25 26 LIC | 1 1 1 1 4 57 CAT 56 |
| ON'T LOOS SOURCE LOOS | 0 0 0 3 8 7 0 1 1 1 6 8 2 8 | 1 1 3 0 8 2 9 |
| EVENT DESCRIPTION AND PROD 0 2 During the review | of the response to an internal inciden | t report, it was |
| 0 3 determined that gr | rab samples were not taken at the requi | red frequency as |
| 0 4 required by Action | n 101 associated with LCO 3.3.7.10 whil | e the RHR Service |
| 0 5 Water System moni | tor was out of service. An initial sam | ple was taken, but |
| 0 6 repeat samples at | eight hour intervals were not made whi | le the monitor was |
| 0 7 out of service. | There were no adverse consequences in t | that no activity was |
| SYSTEM | | mp. VALVE |
| 0 9 W G 11 | 11 12 13 19 | Z 15 Z 16 |
| LER/RO EVENT YEAR 17 REPORT 8 2 21 22 ACTION FUTURE EFFECT ON PLANT H 18 Z 9 Z 20 33 34 35 | CODE TY CODE | PRIME COMP. COMPONENT MANUFACTUREP 22 Z 25 Z 9 9 9 9 |
| CAUSE DESCRIPTION AND COR | up was notified by Operations to take a | a sample, but was not |
| informed that the | sampling was to be done in response to | a Technical Specifi- |
| 1 2 cation action sta | tement which required subsequent sampli | ing. Operations per- |
| sonnel will be in | structed that initiation and termination | on of LCO sampling |
| | ed by the Shift Supervisor. | |
| PACILITY STATUS POWER | other status 30 METHOD OF DISCOVERY n/a A 31 internal re | ERY DESCRIPTION 32) |
| 1 6 Z 33 Z 34 II | | N OF RELEASE 36 |
| PERSONNEL EXPOSURES NUMBER TYPE DESC 1 7 0 0 0 37 Z 38 | n/a | |
| PERSONNEL INJURIES NUMBER DESCRIPTION | n/a | |
| LOSS OF OR DAMAGE TO FACILITY | | |
| PUBLICITY ISSUED DESCRIPTION 45 | n/a | NRC USE ONLY |
| NAME OF PREPARE | | (717) 542-2181 X240 |
| WANE OF FREFARE | 711011 | |