## NRC FORM 591 PART 1 (7-91)

U.S. NUCLEAR REGULATORY COMMISSION

10 CFR 2.201	SAFETY IN	SPECTION	Page 1 of/_
1. LICENSEE S.K. McBryde, Inc. P.O. Box 579 Summerfield, North Carolina		REGIONAL OFFICE  REGION II  U S NUCLEAR REGULAT  101 MARIETTA STREET N  ATLANTA GA 30323	
3. DOCKET NUMBER(\$) 030-32095	4 LICENSE NUMBER(S) 32-25137-01	5. DATE OF INS	6/94
LICENSEE The inspection was an examination of the act Regulatory Commission (NRC) rules and regulatory and representative records, intervitollows	lations and the conditions of ews with personnel, and obse	your license. The inspection consisted	of selective examinations of
questions on those actions at this ti	you have taken to correct the ne. r activities, as described belo	e violations identified during the last in w or attached, were in violation of NRC lance with 10 CFR 19.11.	
indicate the presence of a			not properly posted to CFR 20.203(b),(c),(d),(e) or 34.42. ealed sources were not
C. Records of	or License Condition Num	ber	ere not properly maintained.
		ber	e not made in accordance with
9406270182 9405 PDR ADDCK 0303 C	2095 PDR		
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.	made in accordance with the	ector will be taken to correct the violati e requirements of 10 CFR 2.201. No fu	ons identified in the items checked rther response will be submitted
SIGNATURE - LICENSEE	DATE SI	GNATURE - NRC INSPECTOR	DATE 5/86/94

NRC FORM 591 Part 1 (7-91)