

Appendix

NOTICE OF VIOLATION

Community Memorial Hospital

License No. 48-17740-01

As a result of the inspection conducted on November 9, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

10 CFR 35.14(e)(1)(i) requires that your 208 microcurie cesium-137 calibration sealed source be tested for leakage and/or contamination at intervals not to exceed six months.


Contrary to the above, the referenced sealed source was not leak tested between November 1980 and December 1981.

This is a Severity Level V violation (Supplement VI).

The inspection showed that action had been taken to correct the identified item of noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required and we have no further questions regarding this matter.

11-23-82

Dated



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1