

DCD/DCB

JAN 2 1991

Radiation Sterilizers, Inc.
ATTN: Barry Fairand, Ph.D.
Corporate Radiation Safety
Officer
4020 Clipper Court
Fremont, CA 94538

License No. 04-19644-01
Docket No. 030-19025

Gentlemen:

This refers to the special safety inspection conducted by Mr. J. L. Lynch of this office on December 11, 1990 of activities authorized by NRC Byproduct Material License No. 04-19644-01 and to the discussion of our findings with you and Mr. J. T. Robison at the conclusion of the inspection.

This inspection was conducted to evaluate the WESF capsule removal process at the Westerville, Ohio facility. The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, independent measurements and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection, however, an open item regarding the labeling of transport casks was identified. This item must be closed out prior to any future shipments of WESF capsules.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

William H. Schultz, Chief
Nuclear Materials Safety
Section 1

Enclosure: Inspection Report
No. 030-19025/90001(DRSS)

cc w/enclosure:
J. T. Robison, General Manager
DCD/DCB (RIDS)

RIII
[Signature]
Lynch/lh

RIII
[Signature]
Schultz
1-2-91

IXO 7