JAN 02 1991

Docket No. 030-20108

License No. 06-00483-10

Wesleyan University ATTN: William Firshein, Ph.D. Chairman, Department of Chemistry Middletown, Connecticut 06457

Gentlemen:

Subject: Routine Inspaction No. 030-20108/90-001

On November 14, 1990, Eric H. Reber of this office conducted a routine safety inspection at the above address of activities authorized by the above listed NRC license. The inspection was an examination of your licensed activities as they relate to radiation safety and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selective examination of representative records. The findings of the inspection were discussed with you and Donald Albert at the conclusion of the inspection.

Based on the results of this inspection, it appears that your activities were not conducted in full compliance with NRC requirements. A Notice of Violation is enclosed as Appendix A and categorizes scan violation by severity level in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy). You are required to respond to this letter and in preparing your response, you should follow the instructions in Appendix A.

From the discussion of our findings at the conclusion of the inspection, we understand that you will formally request that your license be amended to allow you to nold radioactive material with a physical half-life of less than some specified amount of time for decay-in-storage before disposal in ordinary trash. Please confirm our understanding in your reply to this letter.

Item A.2 in the Notice of Violation enclosed with this letter was identified during a previous inspection of your licensed activities and documented in a Notice of Violation enclosed with our letter dated January 7, 1986. From this inspection, it appears that your corrective actions were not effective since this item has recurred. Recurrent and uncorrected violations are given additional weight in the consideration and selection of appropriate enforcement action. Therefore, in your response to this letter, you should give particular attention to those actions taken or planned to ensure that identified items of noncompliance will be completely corrected and will not recur.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

OFFICIAL RECORD COPY

ML DL WESLEYAN - 0001.0.0 12/11/90

9101110130 910102 REGI LIC30 06-00483-10 PDR

RETURN ORIGINAL TO REGION I

IE:07

Wesleyan University

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By: John D. Kinneman

John D. Kinneman, Chief Nuclear Materials Safety Section B Division of Radiation Safety and Safeguards

Enclosure: Appendix A, Notice of Violation

CC:

Public Document Room (PDR) Nuclear Salety Information Center (NSIC) State of Longecticut

bcc:

Region I Docket Room (w/concurrences) Management Assistant, DRMA

RI: DRSS Rebertbj



12/2/90

12/11/90 OFFICIAL RECORD COPY

ML DL WESLEYAN - 0001.1.0 12/11/90