CLEAR REQULATOR	SAFEGUARDS	DRY COMMISSION N II , N.W., SUITE 2900	
	ATDANTA, GEOM	30.32.3-0188	
Report Nos. 50	-325/94-13 and 50-324/94-1	3	
P. 0	lina Power and Light Compa Box 1551 igh, NC 27602	iny	
Docket Nos. 50	325 and 50-324	License Nos.	DPR-71 and DPR-6
Facility Name:	Brunswick Steam Electric Units 1 and 2	Generating Plant	
Inspection Condu	icted: May 16 - 20, 1994		
Inspector: W. J.	Ilian Isin Tobin, Sinior Safeguards	Inspector	6/16/97 Date Signed
Approved by:	29h. Aus		6/16/94
	R. McGuire, Chief Eguards Section		Date Signed
	ear Materials Safety and	Safeguards Branch	

SUMMARY

Division of Radiation Safety and Safeguards

Scope:

This routine, announced inspection was conducted in the area of the Physical Security Program for Power Reactors. Specifically Corrective Actions/Management Support, Security Plans/Procedures, Vital Area Access Controls, Alarm Stations/Communication, and, Training/Qualification were reviewed. Additionally, Control of Safeguards Information was reviewed. Corrective action to prior inspection results (No. 92-21-03 and No. 93-33-01) were also evaluated.

Results:

PDR

ADOCK 05000324

PDR

One violation was identified relative to loss of a security emergency key issued to auxiliary operators, (No. 94-13-01, see paragraph 3.c). A non-cited violation was identified relative to control of safeguards information (No. 94-13-02, see paragraph 4). Prior items No. 93-33-01, failure to conduct a drug test (see paragraph 2.a), and No. 92-21-03, protection of safety related equipment (see paragraph 2.b) were closed. Safeguard Event Logs and Adverse Condition Reports revealed that a significant proportion of security violations have been caused by non-security personnel failures, i.e. vital area doors left unsecured, badges removed from the protected area, and escorts loosing control of visitors. For this reason, Inspector Followup Item No. 93-47-01, "human error root cause of safeguards events" (see paragraph 3.a) will be left open.

Alarm station operations and training have been significantly improved and are strengths in an overall good security program. 7406270245 940616 UARDS INFORMATION

contains sensitive unclassified information. When separated from enclosures, this document is decontrolled

2